
olo

व्यावसायिक परीक्षण रिपोर्ट COMMERCIAL TEST REPORT

संख्या/ No.: ROTAVATOR-308/2577/2020

माह/Month: November, 2020

THIS TEST REPORT VALID UP TO : 30th November, 2027



CEPPL, STD 7 FT + ROTAVATOR (TRACTOR MOUNTED)



भारत सरकार

Government of India कृषि एवं किसान कल्याण मंत्रालय

Ministry of Agriculture and Farmers Welfare

कृषि, सहकारिता एवं किसान कल्याण विभाग

Department of Agriculture, Cooperation and Farmers Welfare उत्तरी क्षेत्र कृषि मशीनरी प्रशिक्षण एवं परीक्षण संस्थान

Northern Region Farm Machinery Training and Testing Institute

ट्रैक्टर नगर, सिरसा रोड, हिसार, (हरियाणा) - 125 001

Tractor Nagar, Sirsa Road, HISAR (Haryana)-125 001 [ISO 9001:2015 CERTIFIED]

Website: http://nrfmtti.gov.in/

E-mail: fmti-nr@nic.in

Tele./FAX: 01662-276984

Page 1 of 22

CEPPL, STD 7FT+ ROTAVATOR (TRACTOR MOUNTED) (COMMERCIAL)

4.11 Lubricants:

Sl. No.	Particulars	As recommended by the manufacturer	As used during test	
1	Primary Gear box	SAE 85W 140	Oil originally filled in	
2	Secondary Gear box	SAE 85W 140	the rotavator was not changed	
3	Rotor Hub	Not specified	CREAT LAND	
4	Propeller Shaft	Not specified	M.P. Grease	

5. RUNNING - IN

Rotavator was run in for 1.72 hour before field performance test.

6. LABORATORY TEST

6.1 Hardness: - The surface hardness of blade was recorded as under: -

Description	As per IS: 6690:1981 (HRC)	Hardness as observed (HRC)	Remarks
Edge portion	53 to 59	44	Does not conform
On shank portion	37 to 45	44	Conforms

6.2 Chemical composition

The chemical composition of blades is tabulated as under:-

Constituents	S As per IS: 6690-1981 Carbon Silicon Steel Manganese steel		Composition	Remarks
			as observed (% of weight)	n wil gi
Carbon (C)	0.70 -0.85	0.50-0.60	0.1528	Does not conform
Silicon (Si)	0.10 -0.40	1.50-2.00	0.2936	Conforms to carbon steel
Manganese (Mn)	0.50 -1.0	0.50-1.00	1.7117	Does not conform
Sulphur (S)	0.05(max)	0.05(max)	0.0305	Conforms
Phosphorous (P)	0.05(max)	0.05(max)	0.0145	Conforms

7. FIELD PERFORMANCE TEST

The field tests of the rotavator comprising of Dry land and Wet land operation were conducted for 25 and 10 hours respectively to assess the performance test is reported in **Annexure-I & II** for dry land and wet land operation respectively.

Observations of field performance test is summarized in the ensuing table:-



CEPPL, STD 7FT+ ROTAVATOR (TRACTOR MOUNTED) (COMMERCIAL)

Summary of Field Performance Test

Sl. No.	Parameters/operations	Dry land operation	Wet land operation (Puddling)		
I	II SECTION	Ш	IV		
1.	Tractor used	Farmtrac, FT-60 LHL			
2.	Gear used	L-1 L-1			
3.	Type of soil	Sandy	loam		
4.	Average soil moisture (%)	2.4 to 3.13			
5.	Average depth of standing water (cm)	=7	10.63 to 10.78		
6.	Bulk density of soil (g/cc)	1.586 to 1.710	21		
7.	Average speed of operation (kmph)	2.44 to 2.60	2.32 to 2.37		
8.	Avg. travel reduction (%)	- W	-0.72 to 1.02		
9.	Avg. wheel slip (%)	-3.89 to -1.39	-		
10.	Average depth of puddle (cm)	7	25.44 to 26.11		
11.	Average depth of cut (cm)	10.56 to 11.00			
12.	Avg. effective width (cm)	186 to 189			
13.	Area covered (ha/h)	0.385 to 0.424	**		
14.	Time required for one ha (h)	2.36 to 2.54			
15.	Field efficiency (%)	83 to 86	22		
16.	Puddling index (%)		80.95 to 81.25		
17.	Fuel consumption				
	1/h	5.0 to 6.4	1.86 to 2.22		
	l/ha	12.70 to 15.10	20)		

7.1 Dry land operation

7.1.1 Rate of work

- i) The rate of work was recorded as 0.385 to 0.424 ha/h, and the speed of operation varies from 2.44 to 2.60 kmph.
- ii) The time required to cover one hectare was recorded as 2.36 to 2.54 h

7.1.2 Quality of work

- i) The depth of operation was recorded as 10.56 to 11.00 cm.
- ii) Average effective width was observed as 186 to 189 cm.
- iii) Field efficiency was observed as 83 to 86 %.

7.2 Wet Land operation

7.2.1 The tractor was fitted with half cage wheel on rear pneumatic traction wheel for conducting the puddling operation. The brief specification of half cage wheel is given in Annexure-III

7.2.2 Quality of work

- i) The depth of puddle was recorded as 25.44 to 26.11 cm.
- ii) The puddling index was recorded as 80.95 to 81.25 %.

17 of 22

CEPPL, STD 7FT+ ROTAVATOR (TRACTOR MOUNTED) (COMMERCIAL)

7.3 Labour requirement

In all, two skilled operators are needed to ensure continuous operation of rotavator for day long period.

7.4 Wear analysis (on mass basis)

Wear of hatchet blades (on mass basis) was measured and recorded in ensuing table:

Percentage wear of rotavator blades on mass basis

SI. No.	Initial mass of blade (g)	Mass of blade after 36.96 hr. of operation (g)	Difference of weight (g)	Percentage of wear (%) after 36.96 hr.	Percentage of wear on hour basis (%)
1.	1000.8	900.1	100.7	10.06	0.27
2.	1004.6	911.9	92.7	9.23	0.25
3.	1002.8	900.7	102.1	10.18	0.28
4.	999.1	899.6	99.5	9.96	0.27
5.	1003.5	902.9	100.6	10.02	0.27
6.	997.6	889.2	108.4	10.87	0.29
7.	1000.4	897.3	103.1	10.31	0.29
8.	964.1	889.0	75.1	7.79	0.21

8. EFFECTIVENESS OF SEALINGS

After completion of wet land operation for 10 hours, the rotavator was dismantled for checking the effectiveness of sealing provided against ingress of dust, and water/mud in various sub-assemblies/components. The observations are given in ensuing table:-

Sl. No.	Location	Whether ingress of mud and/or water was observed (Yes/No)
1.	Primary reduction gear box	No
2.	Secondary reduction gear box	No
3.	Rotor assembly (hub)	No

9. EASE OF OPERATION & ADJUSTMENTS

No noticeable difficulty was observed during the operation and adjustment of rotavator.

10. DEFECTS, BREAKDOWN AND REPAIRS

No noticeable defect or breakdown was observed during the test.

11. CRITICAL TECHNICAL SPECIFICATION

Deferred till 31.12.2020 vide Ministry O.M. No 13-13/2020 M&T, (I&P) dated 24.04.2020

12. COMMENTS AND RECOMMENDATIONS

- 12.1 The Dimension of three point linkage of implement does not conform, in toto, to the requirements of IS: 4468(Part-1)-1997 and therefore, it may be looked into for corrective action.
- 12.2 The provision against overload on P.T.O drive shaft is not provided. It MUST be provided.
- 12.3 The grade of grease is not specified. It MUST be specified.
- 12.4 The hardness of blades does not conform, in toto, to the requirements of IS: 6690-1981. This needs to be looked into for corrective action.
- The chemical composition of blades does not conform, in toto, to the requirements of IS: 6690-1981. This needs to be looked into for corrective action.
- Applicant has recommended the suitable tractor size as "45 HP" however the labeling plate of the tractor provided by manufacturer has not declared the maximum P.T.O power in it. Necessary action may be taken for guidance's of users.

12.7 Technical Literature:

One technical booklet "without any title on it", was provided with the rotavator during testing. The same needs to be revised, upgraded and updated as per IS: 8132-1999.

TESTING AUTHORITY

SANJAY KMAR AGRICULTURAL ENGINEER	Skirmal
P. K. PANDEY DIRECTOR	U3n-00086

13. APPLICANT'S COMMENTS

Para No.	Our Ref.	Applicant Comments
13.1	12.1	Corrective action has already been initiated at design end to meet all the dimensions of three point linkage of implement to conform IS:4468(Part-1)-1997. This will definitely introduce in further production.
13.2	12.2	Action has initiated to make sure that the future supply of PTO shafts will have the provision of shear bolt to avoid any effect of overload on tractor.
13.3	12.3	Grade of grease is NLGI Grade-3
13.4	12.4	Action initiated at manufacturer end for conformance to the raw material standard and inspect the process to maintain the hardness of the blade to conform IS:6690-1981
13.5	12.5	Corrective action initiated at manufacture end by inspect raw material to maintain the chemical composition of material as per IS:6690-1981. This will be incorporated for next lot
13.6	12.6	The recommended tractor HP-45 has been mentioned, However PTO power was not on the tractor label plate. In such cases we suggest to check the testing report of the tractor before engaging with the implement and make sure that the PTO power of the tractor is as per our recommendation.
13.7	12.7	Updation of technical booklet has been initiated. The book will be revised and updated to conform IS:8132:1999. All the recommendations will be taken seriously and improvements will be done at war footing level.